



the old rectory

Client: Mr. and Mrs. W Hay

In association with Nicholas Symes Associates, Chartered Surveyors

- Restoration of a fire damaged property
- Recording of original structure
- Sympathetic restoration of listed building
- Close communications with builders

Brief:

Sadler Architects were commissioned to restore a building that had been severely ravaged throughout by fire.

Solution:

Conducting an intensely detailed survey, SA recorded the positions of the timber frame in order to correctly restore the building. Using CAD, the building was reconstructed beam by beam with the final drawings meeting the requirement for listed building consent and building regulations.

Result:

The result, as the pictures show, is a full and seamless restoration of a grade II listed building to a high standard.



Before the fire



After the fire



Interior and exterior pictures following the extensive restoration.

